

DATUM / DATE : 25.09.2012

SUBJECT: STANOVENÉ INTERVALY DO GENERÁLNÍ OPRAVY (GO)
REQUIRED TIME BETWEEN OVERHAULS (TBO) INTERVALS

PROPELLER MODEL AFFECTED: KW-20, KW-21, VAR 2, VAR 3, VAR P, SR 200-J/2, SR 200-J/3, SR 200, SR 116, SR 3000/2, SR 3000/3, SR 3000-J/2, SR 3000-J/3, SR 2000, SR 2000D, SR 3000N-E/2, SR 3000N-E/3, VARIA 165, VARIA 170, WINGLET 136, WINGLET 175, DIRECT 136, PROPULS AE, PROPULS AES, KLASSIC 160, KLASSIC 170, EFFIC 170

SERIAL NUMBERS AFFECTED: All serial numbers / Všechna sériová čísla

SERVICE MANUAL AFFECTED:

Users Manuals of the propellers type / Uživatelské manuály vrtulí:

KW-20, KW-21, VAR 2, VAR 3, VAR P, SR 200-J/2, SR 200-J/3, SR 200, SR 116, SR 3000/2, SR 3000/3, SR 3000-J/2, SR 3000-J/3, SR 2000, SR 2000D, SR 3000N-E/2, SR 3000N-E/3, VARIA 165, VARIA 170, WINGLET 136, WINGLET 175, DIRECT 136, PROPULS AE, PROPULS AES, KLASSIC 160, KLASSIC 170, EFFIC 170

REASON:

This Service Bulletin determines overhaul intervals for all WOODCOMP propellers.

Tento Servisní bulletin stanovuje intervaly generálních oprav u všech vrtulí firmy WOODCOMP.

Propeller Model	TBO	
	operating (oper. hours)	calendar (months)
Fixed wooden propellers / Pevné vrtule KR, ser., SR, ser.	3000	120
KW-20	1200	60
KW-21	1200	60
VAR 2	1000	60
VAR 3	1000	60
VAR P	750	60
SR 200-J/2	750	48
SR 200-J/3	750	48
SR 200	1000	60
SR 116	1000	60
SR 3000/2	1000	60
SR 3000/3	1000	60
SR 3000-J/2	750	48
SR 3000-J/3	750	48
SR 2000	1000	60
SR 3000N-E/3	1200	72
SR 3000N-E/2	1200	72



SERVISNÍ BULLETIN / SERVICE BULLETIN
No. 02/2012

Page : 2
Pages: 2

Propeller Model	TBO	
	operating (oper. hours)	calendar (months)
Varia 165	1000	60
Varia 170	1000	60
Winglet 136	1000	60
Winglet 175	1000	60
Direct 136	1000	60
Propuls AE	1000	60
Propuls AES	1000	60
Klassic 160	1000	60
Klassic 170	1000	60
Effic 170	1000	60



Manager Accountable
Name: Aleš Křemen
Sign:

Date:
24.09.2012

New edition